

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad

Location ID: 324452



Photo # 9757 From entrance to location




Photo # 9758 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad

Location ID: 324452



Photo # 9759 Location




Photo # 9760 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad

Location ID: 324452



Photo # 9761 Location




Photo # 9762 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad

Location ID: 324452



**Photo # 9763 Tank failure/Tank lacks integrity**



**Photo # 9764 Tank failure/Tank lacks integrity**

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad

Location ID: 324452




Photo # 9765 Tank failure/Tank lacks integrity



Photo # 9766 Tank failure/Tank lacks integrity

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad

Location ID: 324452



Photo # 9767 Tank failure/Tank lacks integrity



Photo # 9768 Tank failure/Tank lacks integrity

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad

Location ID: 324452



Photo # 9769 Tank failure/Tank lacks integrity



Photo # 9770 Tank failure/Tank lacks integrity

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad

Location ID: 324452



**Photo # 9771 Tank failure/Tank lacks integrity**