

Inspection Photos

API: 071-09018

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/16/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo facing north along the access road.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09018 | Date: 3/16/2026

Inspection Photos



Photo 2. Drone aerial photo facing northwest toward the access road and location.



Inspection Photos



Photo 3. Drone aerial photo facing northwest overlooking the location.

