

INSPECTION PHOTOS

Well: HILL RANCH 22-12V

API #: 05-071-07211

INSPECTION DOC #: 716302052

Operator: OGRIS OPERATING LLC 10758

Inspection date: 3/18/2026

County: Las Animas



OGRIS
OPERATING, LLC

719-497-0446

or 911

WDID 1912251
PERMIT 74055

HILL RANCH 22-12V

NW/SW 22-34S-67W

NAD 83

Lat. 37.066706

Long. 104.880555

API# 05-071-07211

Network: Mar 18, 2026 at 2:14:42 PM MDT
Local: Mar 18, 2026 at 2:14:42 PM MDT
+37.066734, -104.880793

PHOTO 2: WELL SIGN




Network: Mar 18, 2026 at 2:09:38 PM MDT
Local: Mar 18, 2026 at 2:09:38 PM MDT
+37 066854,-104.881183

PHOTO 3: LOCATION.



Network: Mar 18, 2026 at 2:09:58 PM MDT
Local: Mar 18, 2026 at 2:09:58 PM MDT
+37.066696, -104.880674

PHOTO 4: WELLHEAD AND EQUIPMENT.



Network: Mar 18, 2026 at 2:11:21 PM MDT
Local: Mar 18, 2026 at 2:11:21 PM MDT
+37.066704, -104.880639

PHOTO 5: AREA OF IMPACTED SOIL NEAR WELLHEAD APPEARS TO BE FROM LEAKING DRIVEHEAD. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. THIS IS THE SECOND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED.



PHOTO 6: LEAKING DRIVEHEAD. COMPLY WITH RULE 1002,.(2).D. THIS IS THE SECOND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED.



Network: Mar 18, 2026 at 2:16:39 PM MDT
Local: Mar 18, 2026 at 2:16:39 PM MDT
+37.066657, -104.880589

PHOTO 7: UNUSED EQUIPMENT (LARGE POLLY PIPE AND 2" POLLY PIPE AND EDGE OF PIT). REMOVE UNUSED EQUIPMENT PER RULE 606. CA DATE 3/24/2026.



PHOTO 8: UNUSED EQUIPMENT (PIPE ON EDGE OF PIT). REMOVE UNUSED EQUIPMENT PER RULE 606. CA DATE 3/24/2026.



Network: Mar 18, 2026 at 2:15:49 PM MDT
Local: Mar 18, 2026 at 2:15:49 PM MDT
+37.066732, -104.880712

PHOTO 9: UNUSED EQUIPMENT (HYDRALIC HOSE NEAR PRIME MOVER SOUND WALLS). REMOVE UNUSED EQUIPMENT PER RULE 606. CA DATE 3/24/2026.



PHOTO 10: UNUSED EQUIPMENT (2 PRIME MOVER HEADERS). REMOVE UNUSED EQUIPMENT PER RULE 606. CA DATE 3/24/2026.



Network:Mar 18, 2026 at 2:14:00 PM MDT
Local:Mar 18, 2026 at 2:14:00 PM MDT
+37.066817,-104.880824

PHOTO 11: NO WILDLIFE PROTECTION INSTALLED ON 30 BBL INGROUND PRODUCED WATER TANK VENT. **INSTALL BIRD PROTECTOR SCREEN OR OTHER DEVICE TO PROTECT WILDLIFE PER RULE 608b.(7). CA DATE 3/24/2026.**