

Inspection Photos

Location Name: FOSS-USX AA-66N63W/5NESW

Location #: 310381



Photo #1

Foss-USX AA 5-11 (123-26327) Wellsite

Temporarily Abandoned | TA

CA: Undesirable weeds



Photo #2

Foss-USX AA 5-11 Wellsite

Temporarily Abandoned | TA

macro view

CA: Undesirable weeds



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: FOSS-USX AA-66N63W/5NESW

Location #: 310381



Photo #3

Foss-USX AA 5-11 Wellsite
Temporarily Abandoned | TA
Wellsite(s) entrance



Photo #4

Foss-USX AA 5-11 Battery site
Abandoned: ALL Equipment Removed
Formerly served:
Foss - USX AA 5-25; Plugged & Abandoned | PA
prior photo



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources