

Inspection Photos

Location Name: FOSS - USX AA-66N63W/5SWSW

Location #: 306382



Photo #1

Foss - USX AA 5-25 (123-24562) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 25 yds.



Photo #2

Foss-USX AA 5-11 Battery site

Abandoned: ALL Equipment Removed

Formerly served:

*Foss - USX AA 5-25; Plugged & Abandoned | PA
prior photo*



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources