

Final Reclamation Inspection

March 17, 2026

Operator: HOSS* ROBERT L - 41170

Location ID: 405071

Inspection Document #: 697506073

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: STATE 60-4325 #1

Location ID: 405071




Photo 1. Aerial imagery illustrates the approximate location of cable wire, which is ~90 yards northwest of the DA well.



Inspection Photos
Location Name: STATE 60-4325 #1
Location ID: 405071



Photo 2. Photo illustrates cable wire, which is ~90 yards northwest of the DA well.