

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #19 PAD

Location ID: 315812

Date: 03/9/2026



Photo # 2919 Entrance to location




Photo # 2925 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #19 PAD

Location ID: 315812

Date: 03/9/2026



Photo # 2920 Location



Photo # 2924 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #19 PAD

Location ID: 315812

Date: 03/9/2026



Photo # 2936 NW corner of location



Photo # 2937 SW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #19 PAD

Location ID: 315812

Date: 03/9/2026



Photo # 2938 SE corner of location



Photo # 2939 NE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #19 PAD

Location ID: 315812

Date: 03/9/2026




Photo # 2941 Debris



Photo # 2942 Debris

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #19 PAD

Location ID: 315812

Date: 03/9/2026



Photo # 2944 Debris



Photo # 2945 Debris