

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 34-4 Pad

Location ID: 334654



Photo # 9587 From entrance to location




Photo # 9588 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 34-4 Pad

Location ID: 334654



Photo # 9589 Location




Photo # 9590 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 34-4 Pad

Location ID: 334654



Photo # 9591 Location



Photo # 9592 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 34-4 Pad

Location ID: 334654



Photo # 9593 Location



Photo # 9594 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 34-4 Pad

Location ID: 334654



Photo # 9595 Location



Photo # 9596 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 34-4 Pad

Location ID: 334654



Photo # 9597 Tank disconnected & not in use/unused equipment



Photo # 9598 Tank disconnected & not in use/unused equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 34-4 Pad

Location ID: 334654



Photo # 9599 Tank disconnected & not in use/unused equipment