

# Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC F V LARSON #B-22X PAD

Location ID: 314785

Date: 03/16/2026



Photo # 3138 Entrance to location



Photo # 3139 Location

# Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC F V LARSON #B-22X PAD

Location ID: 314785

Date: 03/16/2026



Photo # 3140 Location

Photo # 3147 Location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC F V LARSON #B-22X PAD

Location ID: 314785

Date: 03/16/2026



Photo # 3149 SW corner of location



Photo # 3150 NW corner of location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC F V LARSON #B-22X PAD

Location ID: 314785

Date: 03/16/2026



Photo # 3151 NE corner of location



Photo # 3152 SE corner of location