

Final Reclamation Inspection

March 17, 2026

Operator: KLABZUBA OIL & GAS INC - #10148

Location ID: 393622

Inspection Document #: 697506077

Morgan County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: ROARK #1
Location ID: 393622



Photo 1. Photo taken from the well location, facing North. Photo illustrates erosion control blanket with vegetative establishment. The well location meets Rule 1004 vegetative standards. The well location and access road vegetation was equal to the reference area vegetation.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: ROARK #1
Location ID: 393622



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: ROARK #1
Location ID: 393622



Photo 5. Close up photo taken from the well location. See comments under Photo 1.



Photo 6. Photo taken from the access road, facing West. See comments under Photo 1.

Inspection Photos
Location Name: ROARK #1
Location ID: 393622



Photo 7. Reference photo taken south of the location, facing South.



Photo 8. Close up reference photo illustrating perennial vegetative establishment.

