

# Inspection Photos

March 19th, 2026

Operator: Logos Operating

Location ID: 325216

Inspection Document #: 714003518

County: La Plata

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: McKeen 1



**Photo 1.** View of the project area taken from the access road taken from the western edge facing east.

Inspection Photos  
Location Name: McKeen 1

March 19, 2026  
95° E



**Photo 2.** View of the pad portion of the project area taken from the western edge facing center. Note: surface equipment has been removed.

Inspection Photos  
Location Name: McKeen 1

March 19, 2026  
279° W



**Photo 3.** Cardinal photo taken from the center of the disturbance facing west.



Inspection Photos  
Location Name: McKeen 1

March 19, 2026  
263° W



**Photo 4.** View of location access road taken from the eastern edge of the project area facing west.

Inspection Photos  
Location Name: McKeen 1

March 19, 2026  
53° NE



**Photo 5.** Reference area composed of Rabbitbrush, Sagebrush, Redstem Filaree, Common Yarrow and various bunch grasses. Note: Area has been heavily grazed.

