

Inspection Photos

March 19th, 2026

Operator: Simcoe LLC

Location ID: 326271

Inspection Document #: 714003524

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

March 19, 2026
358° N



Photo 1. View of the active pad taken from the southern edge facing center.

Inspection Photos
Location Name: Richardson G1

March 19, 2026
259° W



Photo 2. View of location cut slope with failing stormwater BMPs.

Inspection Photos
Location Name: Richardson G1

March 19, 2026
214° SW



Photo 3. Failing stormwater BMPs that are not longer functioning on the location cut slope.

Inspection Photos
Location Name: Richardson G1

March 19, 2026
170° S



Photo 4. View of bare soils on location cut slope, additional reclamation efforts are needed in this area.