

# Inspection Photos

March 19th, 2026

Operator: Simcoe LLC

Location ID: 334175

Inspection Document #: 714003522

County: La Plata

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

March 19, 2026  
127° SE



**Photo 1.** View of the active pad taken from the northern edge facing center.

March 19, 2026  
189° S



**Photo 2.** View of surface owner equipment (trailers, etc.) stored on the southern edge of the pad.

March 19, 2026  
75° E



**Photo 3.** View of trailers, tires and various containers with chemicals/oil stored on the active pad.

March 19, 2026  
308° NW



**Photo 4.** Trailers stored on location.



March 19, 2026  
158° S



**Photo 5.** Labels at meter shed and separator equipment are starting to deteriorate.

March 19, 2026  
79° E



**Photo 6.** Irrigation equipment stored on the eastern edge of the disturbance, piping is starting to break up into smaller plastic pieces.