

# Inspection Photos

March 19th, 2026

Operator: Simcoe LLC

Location ID: 306796

Inspection Document #: 714003520

County: La Plata

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Southern Ute P2



Photo 1. View of the active pad taken from the western edge facing center.

March 19, 2026  
53° NE



**Photo 2.** Location access road where stormwater appears to be controlled.