

Inspection Photos

March 19th, 2026

Operator: Simcoe LLC

Location ID: 326650

Inspection Document #: 714003526

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

March 19, 2026
232° SW



Photo 1. View of the active pad taken from the access point edge facing center.

Inspection Photos
Location Name: Cundiff C2

March 19, 2026
353° N



Photo 2. View of location access road, no stormwater issues were observed.

March 19, 2026
245° SW



Photo 3. View of interim reclamation vegetation.