

Inspection Photos

Location Name: FOSS-USX AA-66N63W/5NESW

Location #: 310381



Photo #1

Foss-USX AA 5-11 (123-26327) Wellsite

Temporarily Abandoned | TA

CA: **Undesirable weeds**

prior photo



Photo #2

Foss-USX AA 5-11 Wellsite

Temporarily Abandoned | TA

CA: **Mitigated.**

Undesirable weeds; CLEARED

Operator photo: 2026-03-23



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: FOSS-USX AA-66N63W/5NESW

Location #: 310381



Photo #3

Foss-USX AA 5-11 Wellsite
Temporarily Abandoned | TA

macro view

CA: Undesirable weeds

prior photo



Photo #4

Foss-USX AA 5-11 Wellsite
Temporarily Abandoned | TA *macro view*

CA: Mitigated.

Undesirable weeds; CLEARED

Operator photo: 2026-03-23



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: FOSS-USX AA-66N63W/5NESW

Location #: 310381



Photo #5

Foss-USX AA 5-11 Wellsite
Temporarily Abandoned | TA

Wellsite(s) entrance

prior photo



Photo #6

Foss-USX AA 5-11 Battery site
Abandoned: ALL Equipment Removed

Formerly served:

Foss - USX AA 5-25; Plugged & Abandoned | PA

prior photo



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources