

# INSPECTION PHOTOS

Well: HILL RANCH 26-14

API #: 05-071-09291

INSPECTION DOC #: 716302072

Operator: OGRIS OPERATING LLC 10758

Inspection date: 3/24/2026

County: Las Animas



  
**OGRIS**  
 OPERATING, LLC

**719-497-0446** 6

WDID 1912541 or 911  
 PERMIT 74273

**Hill Ranch 26-14**  
**SE/SW 26-34S-67W**  
**NAD 83**

**Lat. 37.048798**  
**Long. 104.860891**

**API# 05-071-09291**

Network: Mar 24, 2026 at 12:52:04 PM MDT  
 Local: Mar 24, 2026 at 12:52:04 PM MDT  
 +37.048966, -104.861077

PHOTO 2: WELL SIGN



Network: Mar 24, 2026 at 12:51:23 PM MDT  
Local: Mar 24, 2026 at 12:51:23 PM MDT  
+37.048517,-104.860990

PHOTO 3: LOCATION.



Network: Mar 24, 2026 at 12:51:47 PM MDT  
Local: Mar 24, 2026 at 12:51:47 PM MDT  
+37.048808, -104.860872

PHOTO 4: WELLHEAD AND EQUIPMENT.



Network: Mar 24, 2026 at 12:52:48 PM MDT  
Local: Mar 24, 2026 at 12:52:48 PM MDT  
+37.048952, -104.861054

**PHOTO 5: UNUSED EQUIPMENT (PRIME MOVER SKID WITHOUT ENGINE IS NO LONGER IN USE OR USEFUL). REMOVE UNUSED EQUIPMENT PER RULE 606. CA DATE 4/24/2026.**