

INSPECTION PHOTOS

Well: HILL RANCH 26-11V

API #: 05-071-07145

INSPECTION DOC #: 716302074

Operator: OGRIS OPERATING LLC 10758

Inspection date: 3/24/2026

County: Las Animas


OGRIS
OPERATING, LLC

719-497-0446

WDID 1912211 or 911
PERMIT 74046

HILL RANCH 26-11V
NE/SW 26-34S-67W
NAD 83

Lat. 37.052188

Long. 104.858792

API# 05-071-07145

Network: Mar 24, 2026 at 1:12:44 PM MDT
Local: Mar 24, 2026 at 1:12:44 PM MDT
+37.052130,-104.858719

PHOTO 2: WELL SIGN



Network: Mar 24, 2026 at 1:12:16 PM MDT
Local: Mar 24, 2026 at 1:12:16 PM MDT
+37.051800,-104.858499

PHOTO 3: LOCATION.



PHOTO 4: WELLHEAD AND EQUIPMENT.