

# INSPECTION PHOTOS

Well: HILL RANCH 26-09V

API #: 05-071-07359

INSPECTION DOC #: 716302078

Operator: OGRIS OPERATING LLC 10758

Inspection date: 3/24/2026

County: Las Animas



**OGRI**  
OPERATING, LLC

**719-497-0446**

WDID 1912281 or 911  
PERMIT 74066

HILL RANCH 26-09V

NE/SE 26-34S-67W

NAD 83

Lat. 37.023869

Long. 104.852319

**API# 05-071-07359**

Network: Mar 24, 2026 at 1:38:20 PM MDT  
Local: Mar 24, 2026 at 1:38:20 PM MDT  
+37.053828,-104.852140

PHOTO 2: WELL SIGN



Network: Mar 24, 2026 at 1:37:10 PM MDT  
Local: Mar 24, 2026 at 1:37:10 PM MDT  
+37.053725, -104.852551

PHOTO 3: LOCATION.



Network: Mar 24, 2026 at 1:37:32 PM MDT  
Local: Mar 24, 2026 at 1:37:32 PM MDT  
+37.053752, -104.852344

PHOTO 4: WELLHEAD AND EQUIPMENT.



Network: Mar 24, 2026 at 1:38:03 PM MDT  
Local: Mar 24, 2026 at 1:38:03 PM MDT  
+37.053831, -104.852190

**PHOTO 5: OILY WASTE INSIDE PRIME MOVER ENGINE SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 3/25/2026 FOR OILY WASTE, 3/30/2026 TO REMOVE IMPACTED SOIL.**



Network: Mar 24, 2026 at 1:39:24 PM MDT  
Local: Mar 24, 2026 at 1:39:24 PM MDT  
+37.053973, -104.852380

**PHOTO 6: DEAD TREES AND DEBRIS INSIDE AND ON BANK OF PRODUCED WATER PIT. REMOVE TREES AND DEBRIS PER RULE 606. CA DATE 3/30/2026**