

INSPECTION PHOTOS

Well: HILL RANCH 25-05V

API #: 05-071-07361

INSPECTION DOC #: 716302082

Operator: OGRIS OPERATING LLC 10758

Inspection date: 3/24/2026

County: Las Animas



719-497-0446

WDID 1912282 or 911
PERMIT 74067

HILL RANCH 25-05V

SW/NW 25-34S-67W

NAD 83

Lat. 37.056355

Long. 104.843777

API# 05-071-07361

Network: Mar 24, 2026 at 2:53:25 PM MDT
Local: Mar 24, 2026 at 2:53:25 PM MDT
+37.056379,-104.843890

PHOTO 2: WELL SIGN



Network: Mar 24, 2026 at 2:51:13 PM MDT
Local: Mar 24, 2026 at 2:51:13 PM MDT
+37.056128, -104.843450

PHOTO 3: LOCATION.



Network: Mar 24, 2026 at 2:51:31 PM MDT
Local: Mar 24, 2026 at 2:51:31 PM MDT
+37.056306, -104.843609

PHOTO 4: WELLHEAD AND EQUIPMENT.



PHOTO 5: VENT ON PRODUCED WATER TANK DOES NOT HAVE WILDLIFE PROTECTION.