

Inspection Photos

API: 017-07286

Operator: CITATION OIL & GAS CORP

Inspection Date: 3/23/2026

County: KIOWA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west at the location. There is a pipe riser that needs to be removed. The riser is low to the ground and could be a farming hazard.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-07286 | Date: 3/23/2026

Inspection Photos



Photo 2. There is a pipe riser that needs to be removed. The riser is low to the ground and could be a farming hazard.



Inspection Photos



Photo 3. Facing north at the location..



Inspection Photos



Photo 4. Facing south at the location.

