

# Inspection Photos

API: 017-07385

Operator: CITATION OIL & GAS CORP

Inspection Date: 3/23/2026

County: KIOWA



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west at the location. There is a pipe riser that needs to be removed. The riser is low to the ground and could be a farming hazard.



## Inspection Photos



**Photo 2.** Facing southeast at the location. The previous crop cover is uniform. Riser is shown at left side of photo.

