

Inspection Photos
Location Name: Castor LC35-62HN
Location ID: 433165



Photo 1 – Wellhead

Photo 2 – Wellhead

Inspection Photos
Location Name: Castor LC35-62HN
Location ID: 433165



Photo 3 – Wellhead Sign

Photo 4 – Compressor Site

Inspection Photos
Location Name: Castor LC35-62HN
Location ID: 433165





Photo 5 – Unmarked Risers

Photo 6 – Unmarked Risers

Inspection Photos
Location Name: Castor LC35-62HN
Location ID: 433165




Photo 7 – Unused Batteries and Automation Equipment



Photo 8 – Separators

Inspection Photos
Location Name: Castor LC35-62HN
Location ID: 433165




Photo 9 – Unmarked Risers



Photo 10 – ECDs

Inspection Photos
Location Name: Castor LC35-62HN
Location ID: 433165



Photo 11 – Tank Battery




Photo 12 – Unused Parts

Inspection Photos
Location Name: Castor LC35-62HN
Location ID: 433165



Photo 13 – Tank Battery

Photo 15 – Tank Battery Signs

Inspection Photos
Location Name: Castor LC35-62HN
Location ID: 433165




Photo 15 – Unmarked Risers



Photo 17 – Gas Meters