

# Inspection Photos

API: 061-06515

Operator: EOG RESOURCES INC

Inspection Date: 3/23/2026

County: KIOWA




## Inspection Photos



**Photo 1.** Facing northeast toward the location. The four corner post remain and need to be removed.



## Inspection Photos



**Photo 2.** Center of the location facing north.



## Inspection Photos



**Photo 3.** Center of the location facing south.



## Inspection Photos



**Photo 4.** Facing north at the southeast corner. The four corner post need to be removed.



## Inspection Photos



**Photo 5.** Facing east at the surrounding pasture.

