

# Inspection Photos

API: 017-06960

Operator: LOEB LLC\* HERMAN L

Inspection Date: 3/23/2026

County: CHEYENNE



## Inspection Photos



**Photo 1.** Center of the location facing north.. There appears to be impacted crop establishment.



## Inspection Photos



**Photo 2.** Center of the location facing east.



## Inspection Photos



**Photo 3.** Center of the location facing south. There less crop stubble at the location than in the surrounding field.

