

Inspection Photos

API: 017-06982

Operator: LOEB LLC* HERMAN L

Inspection Date: 3/23/2026

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west along the former access road. There is impacted crop establishment.



Inspection Photos



Photo 2. East side of the location facing west. This area with no crop growth is approximately 150 ft x 40 ft.



Inspection Photos



Photo 3. Facing toward the northwest side of the location. There are areas with no crop establishment.



Inspection Photos



Photo 4. West side of the location facing east. This area with no crop growth is approximately 150 ft x 40 ft.



Inspection Photos



Photo 5. Facing north toward the surrounding reference area which has a uniform crop cover.

