

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-65S97W/25NWSW

Location ID: 324304

Date: 3/18/2026



Mar 18, 2026 at 12:45:19  
+39.583633,-108.234520  
De Beque CO 81630  
United States



Mar 18, 2026 at 12:46:43  
+39.583714,-108.233980  
De Beque CO 81630  
United States

Location Overview – Photo #03171

Location – Photo #03175

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-65S97W/25NWSW

Location ID: 324304

Date: 3/18/2026



Location – Photo #03177



Location – Photo #03172

## Audit Photos


Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-65S97W/25NWSW

Location ID: 324304

Date: 3/18/2026



**Wildlife Entry Hazard – Photo #03178**



**Wildlife Entry Hazard – Photo #03179**