

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-65S97W/26SESE

Location ID: 383259

Date: 3/18/2026



Location Overview – Photo #03182



Location – Photo #03186

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-65S97W/26SESE

Location ID: 383259

Date: 3/18/2026



Location – Photo #03183



Location – Photo #03191

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-65S97W/26SESE

Location ID: 383259

Date: 3/18/2026



Weathered/Illegible Wellhead Sign – Photo #03187




Weathered/Illegible Battery Sign – Photo #03192

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-65S97W/26SESE

Location ID: 383259

Date: 3/18/2026



Wildlife Entry Hazard – Photo #03184