

Inspection Photos

03/18/2026

Operator: QB Energy Operating LLC #10844

Location ID: 323937

Inspection Doc: 719200947

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 323937



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 323937



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 323937



Photo 3: Photos showing erosion that is occurring on the eastern edge of the working pad surface; stormwater BMP's appear to be missing or insufficient. Comply with Rule 1002.f.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 323937



Photo 4: Photos showing examples of erosion that is occurring on the western edge of the working pad surface; stormwater BMP's appear to be missing or insufficient. Comply with Rule 1002.f.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 323937



Photo 5: A small subsidence is occurring in the northeastern interim area. Maintenance is required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 323937



Photo 6: Photos showing examples of the northwestern and eastern interim areas, respectively. Interim areas are used by cattle; perennial grasses are present. Interim areas are progressing towards 1003 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 323937



Photo 7: Fill slopes are predominantly bare in some areas, and erosion/rilling is occurring. Additional reclamation efforts may be required in the future to stabilize the slopes.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources