

# Inspection Photos

03/18/2026

Operator: QB Energy Operating LLC #10844

Location ID: 334867

Inspection Doc: 719200953

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334867



**Photo 1:** Photos showing an overview of the location looking north and south, respectively. Grey material is undesirable plant species such as kochia and prickly Russian thistle.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334867



**Photo 2:** Photos showing an overview of the location looking east and west, respectively. Grey material is undesirable plant species such as kochia and prickly Russian thistle.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334867



**Photo 3:** Photos showing examples of twine trash that is scattered throughout the location and requires removal.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334867



**Photo 4:** Photos showing a small patch of Russian knapweed, a List B noxious weed species, is present in the southeastern portion of the location. Weed control efforts are required.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334867



**Photo 5:** Downed fencing allowing cattle access and grazing activities at the location. It is recommended that grazing is not permitted while final reclamation is in process.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334867



**Photo 6:** Photos showing a nearby reference area located directly south across the road from the location. A follow-up inspection will be conducted during future growing seasons to collect additional information regarding the reference area and to evaluate weed control efforts at the location.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources