

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, TRAIL RIDGE-65S97W/35NWSW

Location ID: 335745

Date: 3/18/2026



Location Overview – Photo #03223



Location – Photo #03228

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, TRAIL RIDGE-65S97W/35NWSW

Location ID: 335745

Date: 3/18/2026



Mar 18, 2026 at 13:21:11  
+39.568328,-108.252306  
De Beque CO 81630  
United States



Mar 18, 2026 at 13:24:31  
+39.568327,-108.252208  
De Beque CO 81630  
United States

Location – Photo #03224

Location – Photo #03221

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, TRAIL RIDGE-65S97W/35NWSW

Location ID: 335745

Date: 3/18/2026



Stored Supplies – Photo #03230




Wildlife Entry Hazard – Photo #03225

## Audit Photos


Location Name: TEP ROCKY MOUNTAIN LLC, TRAIL RIDGE-65S97W/35NWSW

Location ID: 335745

Date: 3/18/2026



Wildlife Entry Hazard – Photo #03226



Wildlife Entry Hazard – Photo #03227