

# Inspection Photos

03/18/2026

Operator: QB Energy Operating LLC #10844

Location ID: 323970

Inspection Doc: 719200961

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 323970



**Photo 1:** Photos showing an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 323970



**Photo 2:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 323970



**Photo 3:** Photos showing rilling and erosion that is occurring on the western side of the tank battery equipment. Stormwater BMP's appear to be missing or insufficient; comply with Rule 1002.f.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 323970



**Photo 4:** Photos showing the northern and western interim areas, respectively. Interim areas are patchy in some places; overall interim areas appear to be progressing towards 1003 reclamation requirements.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources