

Inspection Photos

03/18/2026

Operator: QB Energy Operating LLC #10844

Location ID: 334987

Inspection Doc: 719200963

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334987



Photo 1: Photos showing an overview of the location looking northeast and southwest, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334987



Photo 2: Photos showing an overview of the location looking northwest and southeast, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334987



Photo 3: Photos showing an overview of the eastern and northwestern interim areas, respectively. Interim areas are progressing towards 1003 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334987



Photo 4: Photos showing one (1) Russian knapweed individual that is present on the eastern portion of the interim area. Prickly Russian thistle is present in tertiary amounts. Ongoing weed monitoring and management is recommended at this location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334987



Photo 5: Photos showing examples of vehicle rutting and sediment tracking that is occurring on the working pad surface and at the entrance to the location; maintenance is required. Comply with 1002.f.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources