

Final Reclamation Inspection

March 17, 2026

Operator: KLABZUBA OIL & GAS INC - #10148

Location ID: 393787

Inspection Document #: 697506090

Morgan County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: STATE OF COLORADO B-6

Location ID: 393787



Photo 1. Photo taken from the well location, facing North. Photo illustrates vegetation meets Rule 1004 standards with the establishment of perennial, native grasses.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos

Location Name: STATE OF COLORADO B-6

Location ID: 393787



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos

Location Name: STATE OF COLORADO B-6

Location ID: 393787



Mar 17, 2026 14:01:34
ECMC Reclamation

Photo 5. Photo taken along a portion of the access road, facing East. Photo illustrates the access road.



Mar 17, 2026 14:01:44
ECMC Reclamation

Photo 6. Photo taken along a portion of the access road, facing West. See comments under Photo 5.

