

Inspection Photos

Location Name: BASHOR PC AA/09-25

Location #: 420220



Photo #1

Bashor PC AA 09-25 (123-32511) Wellsite

Abandoned Location | AL

≈ 30 yds.

No disturbance / Location never built.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources