

INSPECTION PHOTOS

Well: HILL RANCH 34-06R & V

API #: 05-071-07181

INSPECTION DOC #: 716302086

Operator: OGRIS OPERATING LLC 10758

Inspection date: 3/27/2026

County: Las Animas

API# 05-071-07181



OGRIS
OPERATING, LLC

719-497-0446
or EMERGENCY 911

HILL RANCH 34-06R
API# 05-071-07181-00
SE/NW 34-34S-67W
LAT. 37.042384
LONG. -104.878369



OGRIS
OPERATING, LLC

719-497-0446
or EMERGENCY 911

HILL RANCH 34-06V
API# 05-071-07180-00
SE/NW 34-34S-67W
LAT. 37.042384
LONG. -104.878629

Network: Mar 27, 2026 at 10:21:30 AM MDT
Local: Mar 27, 2026 at 10:21:30 AM MDT
+37.042266, -104.878321

PHOTO 2: WELL SIGN



Network: Mar 27, 2026 at 10:20:35 AM MDT
Local: Mar 27, 2026 at 10:20:35 AM MDT
+37.042037, -104.878328

PHOTO 3: LOCATION.



PHOTO 4: R WELLHEAD AND EQUIPMENT.



Network: Mar 27, 2026 at 10:21:07 AM MDT
Local: Mar 27, 2026 at 10:21:07 AM MDT
+37.042293, -104.878534

PHOTO 5: V WELLHEAD AND EQUIPMENT.