

INSPECTION PHOTOS

Well: HILL RANCH 34-03

API #: 05-071-08886

INSPECTION DOC #: 716302088

Operator: OGRIS OPERATING LLC 10758

Inspection date: 3/27/2026

County: Las Animas


OGRIS
OPERATING, LLC

or 911

HR 34-03 NE/NW

34-34S-67W

NAD 83

Lat. 37.045529

Long. 104.877908

API# 05-071-08886

Network: Mar 27, 2026 at 10:49:26 AM MDT
Local: Mar 27, 2026 at 10:49:26 AM MDT
+37.045530, -104.878113

PHOTO 2: WELL SIGN



Network: Mar 27, 2026 at 10:48:20 AM MDT
Local: Mar 27, 2026 at 10:48:20 AM MDT
+37.045154, -104.877931

PHOTO 3: LOCATION.



Network: Mar 27, 2026 at 10:48:43 AM MDT
Local: Mar 27, 2026 at 10:48:43 AM MDT
+37.045525, -104.878038

PHOTO 4: WELLHEAD AND EQUIPMENT.