

# INSPECTION PHOTOS

Well: HILL RANCH 28-10 & V

API #: 05-071-07022

INSPECTION DOC #: 716302090

Operator: OGRIS OPERATING LLC 10758

Inspection date: 3/27/2026

County: Las Animas



Network: Mar 27, 2026 at 11:25:50 AM MDT  
Local: Mar 27, 2026 at 11:25:50 AM MDT  
+37.053468, -104.889220

PHOTO 2: WELL SIGN



Network: Mar 27, 2026 at 11:25:30 AM MDT  
Local: Mar 27, 2026 at 11:25:30 AM MDT  
+37.053648, -104.889507

PHOTO 3: LOCATION.



PHOTO 4: WELLHEAD AND EQUIPMENT.



PHOTO 5: V WELLHEAD AND EQUIPMENT.