

INSPECTION PHOTOS

Well: HILL RANCH 27-12R & V

API #: 05-071-07183

INSPECTION DOC #: 716302092

Operator: OGRIS OPERATING LLC 10758

Inspection date: 3/27/2026

County: Las Animas

API# 05-071-07183


 (719) 719-497-0446 or 911
OGRIS
OPERATING, LLC
 WDID 1912231
 PERMIT 74048

HILL RANCH 27-12R
NW/SW 27-34S-67W

NAD 83

Lat. 37.053184

Long. 104.880489


 (719) 719-497-0446 or 911
OGRIS
OPERATING, LLC
 WDID 1912230
 PERMIT 71209

HILL RANCH 27-12V
NW/SW 27-34S-67W

NAD 83

Lat. 37.053184

Long. 104.880749

API# 05-071-07183

Network: Mar 27, 2026 at 11:55:42 AM MDT
Local: Mar 27, 2026 at 11:55:42 AM MDT
+37.053220, -104.880629

PHOTO 2: WELL SIGN



PHOTO 3: LOCATION.



PHOTO 4: R WELLHEAD AND EQUIPMENT.



PHOTO 5: V WELLHEAD AND EQUIPMENT.



Network: Mar 27, 2026 at 11:56:41 AM MDT
Local: Mar 27, 2026 at 11:56:41 AM MDT
+37.053192, -104.880423

PHOTO 6: UNUSED EQUIPMENT (PRIME MOVER ENGINE SKIT IS NOT USABLE ON R WELL). THIS TYPE OF WORK CANNOT BE PERFORMED ON LOCATION. REMOVE UNUSED EQUIPMENT PER RULE 606. CA DATE 4/2/2026.



Network: Mar 27, 2026 at 11:57:51 AM MDT
Local: Mar 27, 2026 at 11:57:51 AM MDT
+37.053196, -104.880695

PHOTO 7: ALLTHOUGH IT APPEARS THAT THE CA FROM PREVIOUS INSPECTION WAS ADDRESSED THE CONDITIONS THAT CREATED THE CA STILL EXISTSON V WELL. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. Engineer, operate, and maintain equipment within the manufacturer’s recommended specifications per Rule 608.e. CA DATE 4/2/2026.



PHOTO 8: OILY WASTE IN PRIME MOVER ENGINE SKIDWITHOUT WILDLIFE PROTECTIONS ON R WELL. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 3/28/2026.