

Inspection Photos

Location Name: BASHOR PC AA/09-08

Location #: 420596



Photo #1

Bashor PC AA 09-08 (123-32642) Wellsite

Temporarily Abandoned | TA



Photo #2

Bashor PC AA 09-08 Wellsite

Temporarily Abandoned | TA

macro view



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: BASHOR PC AA/09-08

Location #: 420596



Photo #3

Bashor PC AA 09-08 Wellsite

Temporarily Abandoned | TA

Wellsite(s) entrance



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: BASHOR PC AA/09-08

Location #: 420596



Photo #4

Bashor PC AA 09-08, 09-23 Battery site

Inactive | Shut-down

Equipment Documented; Fac ID: 481647

Formerly served:

Bashor PC AA 09-22; Plugged & Abandoned | PA



Photo #5

Bashor PC AA 09-08, 09-23 Battery site

Inactive | Shut-down

Battery entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources