

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/26/2026

Submitted Date:

03/27/2026

Document Number:

719700545

FIELD INSPECTION FORM

Loc ID 420596 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

20 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420595	WELL	TA	03/11/2020	OW	123-32642	BASHOR PC AA 09-08	TA

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Blue TA tag posted. OOSLAT applied at well, separator(s).		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:
Equipment:			
Type: Emission Control Device	# 0		corrective date
Comment:	Equipment assigned to Tank Battery Fac ID #481647.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 0		
Comment:	Equipment assigned to Tank Battery Fac ID #481647.		
Corrective Action:			Date:
Type: Gas Meter Run	# 0		
Comment:	Equipment assigned to Tank Battery Fac ID #481647.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Pig Station	# 0		
Comment:	Equipment assigned to Tank Battery Fac ID #481647.		
Corrective Action:			Date:

Type: Plunger Lift	# 0		
Comment:	Temporarily Abandoned TA. Equipment removed.		
Corrective Action:			Date:
Type: Ancillary equipment	# 0		
Comment:	Equipment assigned to Tank Battery Fac ID #481647.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Wellhead: w/ Master, casing valves.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.504389,-104.432704
Comment:	Centralized Battery serves 2 Location IDs (420596, 420598). (Well(s): 2: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (481647).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,
Comment:	Equipment assigned to Tank Battery Fac ID #481647.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				
Comment: Equipment assigned to Tank Battery Fac ID #481647.					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 420595 Type: WELL API Number: 123-32642 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Locked-Out, Tagged-Out | LOTO.
Blue TA tag posted.
OOSLAT applied at well, separator(s).
ECMC records last prod: 11/2017.

Form 4 on file. TA date: 02/06/2020. Approved.
DH-Balanced plug.
Form 21 MIT on file. Date: 04/09/2021. Approved.
Form 6A on file. Out-of-Svc Designation. Approved.
Date ceased prod: 02/24/2015.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/06/2026 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments		
Comment	User	Date
<p>Comment 1: This is a WELL audit. Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (420596, 420598). (Well(s): 2: Temporarily Abandoned TA).</p> <p>Centralized Battery formerly served 1 Location ID (420599). (Well(s): 1: Plugged & Abandoned PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (481647).</p> <p>Reference (Associated Well(s), Battery / Facility Audits): A.) Field Audit Report doc. #719700545 and/or Location ID #420596 for TA Well(s) info. B.) Field Audit Report doc. #719700549 and/or Location ID #420598 for TA Well(s) info. C.) Field Audit Report doc. #719700551 and/or Facility ID #481647 for Battery / Facility, Equipment info.</p>	evinsb	03/27/2026
<p>Comment 2: CECMC Audit Report Synopsis:</p> <p>On THU 03/26/2026 at approximately 13:21 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: NOBLE ENERGY INC Location Name: BASHOR PC AA/09-08 Location ID: 420596 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	03/27/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700548	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7496002