

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-65S97W/25SWNW

Location ID: 335916

Date: 3/18/2026



Location – Photo #03256



Location – Photo #03252

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-65S97W/25SWNW

Location ID: 335916

Date: 3/18/2026



Location – Photo #03251



Location – Photo #03261

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-65S97W/25SWNW

Location ID: 335916

Date: 3/18/2026



Stored Supplies – Photo #03255



No Wildlife Egress in Wellhead Cellar – Photo #03257

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-65S97W/25SWNW

Location ID: 335916

Date: 3/18/2026



No Wildlife Egress in Wellhead Cellar – Photo #03258



No Wildlife Egress in Wellhead Cellar – Photo #03259

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-65S97W/25SWNW

Location ID: 335916

Date: 3/18/2026



Wildlife Entry Hazard – Photo #03253



Open-Ended Lines/Wildlife Entry Hazard – Photo #03254