

# INSPECTION PHOTOS

**Well: APACHE CANYON 19-12**

**API #: 05-071-06347**

**INSPECTION DOC #: 716302097**

**Operator: OGRIS OPERATING LLC 10758**

**Inspection date: 3/30/2026**

**County: Las Animas**



**OGRIS**  
OPERATING, LLC

719-497-0446

or 911

WDID 1912181  
PERMIT 74034

APACHE CANYON 19-12

NW/SW 19-34S-67W

NAD 83

Lat. 37.066395

Long. 104.934802

**API# 05-071-06347**

Network: Mar 30, 2026 at 10:53:44 AM MDT  
Local: Mar 30, 2026 at 10:53:44 AM MDT  
+37.066438, -104.935016

PHOTO 2: WELL SIGN



Network: Mar 30, 2026 at 10:52:29 AM MDT  
Local: Mar 30, 2026 at 10:52:29 AM MDT  
+37.066707, -104.934913

PHOTO 3: LOCATION.



Network: Mar 30, 2026 at 10:53:14 AM MDT  
Local: Mar 30, 2026 at 10:53:14 AM MDT  
+37.066432, -104.934749

PHOTO 4: WELLHEAD AND EQUIPMENT.



**PHOTO 5: Vacuum pump observed on well without ECMC approval. Provide ECMC with documentation showing approval of use of vacuum pump. CA DATE 4/15/2026.**