

Final Reclamation Inspection

February 11, 2026

Operator: KIMBARK OIL & GAS COMPANY

Facility ID: 116857

Inspection Document #: 720300152

Morgan County, CO

Isaac Thibedeau
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MESSEX STATE PIT
Facility ID: 116857



Photo 1. Photo taken from the access road near the pit location, facing northeast, showing bare areas from a cattle trail. The access road was not contoured and is still visible.



Photo 2. Photo taken from the access road facing west showing that the access road was not contoured, and a depression is still visible. Desirable vegetation growing, including native grasses and shrubs.



Inspection Photos
Location Name: MESSEX STATE PIT
Facility ID: 116857



Photo 3. Photo taken on the east side of pit location facing west showing an overview of location. Small areas of exposed soil and grass species are slightly stunted.



Photo 4. Photo taken on the east side of pit location facing north showing an overview of location with desirable vegetation growth.

Inspection Photos

Location Name: MESSEX STATE PIT

Facility ID: 116857

Feb 11, 2026
+40.442170,-103.500865
79° E
Merino CO 80741
United States



Photo 5. Photo taken on the east side of the pit, facing east, showing an overview of the area with desirable vegetation growth.

Feb 11, 2026
+40.442130,-103.500913
220° SW
Merino CO 80741
United States



Photo 6. Photo taken on the southwestern side of the pit, facing southwest, showing an overview of the area with desirable vegetation. Some bare soil and erosion are present.



Inspection Photos
Location Name: MESSEX STATE PIT
Facility ID: 116857



Photo 7. Photo taken from west side of the pit facing west. Vegetation around the location are desirable grass and shrub species and some bare soil present.



Photo 8. Photo taken from west side of the pit facing southeast. Vegetation around the location are desirable grass and shrub species.

Inspection Photos
Location Name: MESSEX STATE PIT
Facility ID: 116857



Photo 9. Photo taken from south side of the location facing west. Cattle trail present and vegetation around the location are desirable grass and shrub species.

Inspection Photos
Location Name: MESSEX STATE PIT
Facility ID: 116857



Photo 10. Photo taken from southeast side of the location facing north. See comment under photo 9.

Inspection Photos
Location Name: MESSEX STATE PIT
Facility ID: 116857



Photo 11. Photo taken from the northern edge of location facing south. See comment under photo 5