

Inspection Photos
Location Name: Just Unit 1
Location ID: 317959



Photo 1 Location access rd.

Photo 2 Location, KP Kauffman WO rig.

Inspection Photos
Location Name: Just Unit 1
Location ID: 317959




Photo 3 Wellsite sign.

Photo 4 Rig floor, wellhead, BOP.

Inspection Photos
Location Name: Just Unit 1
Location ID: 317959



Photo 5 Location.

Photo 6 Location.