

Audit Photos


Location Name: TEP ROCKY MOUNTAIN LLC, TEXACO-65S97W/35NWNE

Location ID: 335750

Date: 3/18/2026



Location Overview – Photo #03195



Location – Photo #0

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, TEXACO-65S97W/35NWNE

Location ID: 335750

Date: 3/18/2026



Location – Photo #03215



Location – Photo #03210

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, TEXACO-65S97W/35NWNE

Location ID: 335750

Date: 3/18/2026



Mar 18, 2026 at 13:04:54
+39.574665,-108.240652
De Beque CO 81630
United States



Mar 18, 2026 at 13:04:43
+39.574647,-108.240665
De Beque CO 81630
United States

Location – Photo #03208

Location – Photo #03207

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, TEXACO-65S97W/35NWNE

Location ID: 335750

Date: 3/18/2026



Illegible Wellhead Sign – Photo #03197



Weathered/Illegible Wellhead Sign – Photo #03198

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, TEXACO-65S97W/35NWNE

Location ID: 335750

Date: 3/18/2026



Weathered/Illegible Wellhead Sign – Photo #03199

Weathered/Illegible Wellhead Sign – Photo #03200

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, TEXACO-65S97W/35NWNE

Location ID: 335750

Date: 3/18/2026



Debris – Photo #03214



Debris – Photo #03220

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, TEXACO-65S97W/35NWNE

Location ID: 335750

Date: 3/18/2026



Debris – Photo #03221




Damaged Fencing – Photo #03196

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, TEXACO-65S97W/35NWNE

Location ID: 335750

Date: 3/18/2026



Damaged Fencing – Photo #03206



Damaged Fencing – Photo #03216

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, TEXACO-65S97W/35NWNE

Location ID: 335750

Date: 3/18/2026



No Wildlife Egress – Photo #03201



No Wildlife Egress – Photo #03202

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, TEXACO-65S97W/35NWNE

Location ID: 335750

Date: 3/18/2026



No Wildlife Egress – Photo #03203



No Wildlife Egress – Photo #03204

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, TEXACO-65S97W/35NWNE

Location ID: 335750

Date: 3/18/2026



No Wildlife Egress – Photo #03205



Open-Ended Line – Photo #03217