

Inspection Photos

API: 071-07475

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/30/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest at the access road. The gate has been repaired.



Inspection Photos



Photo 2. There is impacted material shown at red arrows that needs to be cleaned up.



Inspection Photos



Photo 3. There is impacted material shown at red arrows that needs to be cleaned up.



Inspection Photos



Photo 3. Facing northwest toward the wellsite.

