

Inspection Photos

API: 071-09521

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/30/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south at the location. The location has not been recontoured and a steep cut slope remains. Previous corrective action not completed. .



Inspection Photos



Photo 2. Facing southeast at the location. The location has not been recontoured and a steep cut slope remains. Previous corrective action not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos



Photo 3. Facing southeast toward the location standing further back.



Inspection Photos



Photo 4. Facing southeast at the location. The location has not been recontoured and a steep cut slope remains. Previous corrective action not completed.

