

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404602375

Date Received:
03/31/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:
3 of 3 CAs from the FIR responded to on this Form
3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-3779
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
ERIN JOSEPH	970-515-1169	ECMCInspections@Oxy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714300337
Inspection Date: 03/19/2026 FIR Submit Date: 03/24/2026 FIR Status:

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP Company Number: 47120
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID:

Location Name: Number: County:
Qtrqtr: SWSE Sec: 24 Twp: 2N Range: 68W Meridian: 6
Latitude: 40.119071 Longitude: -104.948758

FACILITY - API Number: 05-123-00

Facility ID: 493402

Facility Name: Walsh GU 6-24, U 24-15JI Number:
Facility
Qtrqtr: SWSE Sec: 24 Twp: 2N Range: 68W Meridian: 6
Latitude: 40.119071 Longitude: -104.948758

CORRECTIVE ACTIONS:

1 CA# 211778

Corrective Action: Secure access to excavation in compliance with Rule 913.b.(5).B.i and ECMC Guidance 913.b.(5)B i-v Date: 03/31/2026

Response: CA COMPLETED Date of Completion: 03/31/2026

Operator Comment: SEE ATTACHED LOCATION PHOTOS

ECMC Decision:

ECMC
Representative:

2 CA# 211779

Corrective Action: Operator shall provide an updated Form 27 for Remediation #39057 with a workplan and timeline for remediation of Spill ID 493402.

Date: _____

Response: CA COMPLETED

Date of Completion: 03/31/2026

Operator
Comment:

SEE ATTACHED

ECMC Decision: _____

ECMC
Representative:

3 CA# 211780

Corrective Action: If soil is to be stockpiled on location Operator shall install a sign to denote if the stockpile is clean or contaminated. Prior to spill/remediation closure Operator will collect soil samples from underneath the observed soil stockpile area and surrounding areas where the stockpile has overflowed berms. Manage waste in compliance with Rule 913.b.iv and ECMC Guidance 913.b.(5)B i-v.

Date: 03/31/2026

Response: CA COMPLETED

Date of Completion: 03/31/2026

Operator
Comment:

SEE ATTACHED

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: ERIN JOSEPH

Signed: _____

Title: REGULATORY

Date: 3/31/2026 2:49:03 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404602375	FIR RESOLUTION SUBMITTED
404602411	LOCATION PHOTOS

Total Attach: 2 Files