

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404597697

Date Received:

03/27/2026

Spill report taken by:

Sanchez, Chris

Spill/Release Point ID:

493603

### SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to ECMC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

### OPERATOR INFORMATION

Name of Operator: <u>RAMPIKE RESOURCES LTD</u>	Operator No: <u>10777</u>	<b>Phone Numbers</b>
Address: <u>730 17TH STREET SUITE 999</u>		Phone: <u>(720) 464-7603</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>		Mobile: <u>( )</u>
Contact Person: <u>Neil Sharp</u>		Email: <u>nsharp@rampikeresources.com</u>

Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 404587984

Initial Report Date: 03/19/2026 Date of Discovery: 03/19/2026 Spill Type: Recent Spill

#### Spill/Release Point Location:

QTRQTR SENW SEC 10 TWP 19S RNG 45W MERIDIAN 6

Latitude: 38.420817 Longitude: -102.448380

Municipality (if within municipal boundaries): \_\_\_\_\_ County: KIOWA

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

Check this box if this spill/release is related to a loss of integrity of a flowline, pipeline, crude oil transfer line, or produced water transfer line.

#### Reference Location:

Facility Type: OFF-LOCATION FLOWLINE  Facility/Location ID No 324811

Spill/Release Point Name: Pyles #4  Well API No. (Only if the reference facility is well) 05- -

No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): >=1 and <5 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): 0

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: \_\_\_\_\_

Has the subject Spill/Release been controlled at the time of reporting? Yes

#### Land Use:

Current Land Use: NON-CROP LAND Other(Specify): \_\_\_\_\_

Weather Condition: Sunny

Surface Owner: FEE Other(Specify): Kevin Davis



Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

A release along the Pyles #4 off-location flowline was detected today by ECMC EPS, Chris Sanchez. Mr. Sanchez reported the leak to the Field Supervisor, Dale Hart at ~1:00 PM MTN. The well was immediately shut in and the flowline has been isolated at the wellhead and treater. The release point is ~172' to the NW of the Pyles #4 wellhead. The impacted area is ~42' x 18'; area was immediately fenced off. Clean-up will begin on 3/20/2026. Approximately <5 bbls of oil was released.

**List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):**

**OTHER NOTIFICATIONS**

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
3/19/2026	Kiowa County	Marci Miller	-	Email
3/19/2026	ECMC	Chris Sanchez	-	Chris was on location and emailed
3/19/2026	Surface Owner	Kevin Davis	-	Spoke with him by phone

**REPORT CRITERIA**

**Rule 912.b.(1) Report to the Director (select all criteria that apply):**

No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.

Waters of the State: \_\_\_\_\_ Public Water System: \_\_\_\_\_  
 Residence or Occupied Structure: \_\_\_\_\_ Livestock: \_\_\_\_\_  
 Wildlife: \_\_\_\_\_ Publicly-Maintained Road: \_\_\_\_\_

Yes Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak

Enter the approximate time of discovery \_\_\_\_\_ (HH:MM)  
 Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 \_\_\_\_\_  
 Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? \_\_\_\_\_  
 Enter the Document Number of the Initial Accident Report, Form 22 \_\_\_\_\_  
 Was there damage during excavation? \_\_\_\_\_  
 Was CO 811 notified prior to excavation? \_\_\_\_\_

No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.

Estimated Volume of Impacted Solids (cu. yd.): \_\_\_\_\_

No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:

- The presence of free product or hydrocarbon sheen Surface Water
- The presence of free product or hydrocarbon sheen on Groundwater
- The presence of contaminated soil in contact with Groundwater
- The presence of contaminated soil in contact with Surface water

No	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylight from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.  <input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

### SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: <u>03/27/2026</u>		
<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	_____	_____	<input checked="" type="checkbox"/>
CONDENSATE	<u>0</u>	<u>0</u>	<input type="checkbox"/>
PRODUCED WATER	<u>0</u>	<u>0</u>	<input type="checkbox"/>
DRILLING FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
FLOW BACK FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
OTHER E&P WASTE	<u>0</u>	<u>0</u>	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, including walls &amp; floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
<b>A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit</b>			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): <u>42</u>		Width of Impact (feet): <u>18</u>	
Depth of Impact (feet BGS): <u>5</u>		Depth of Impact (inches BGS): _____	
How was extent determined?			
Extent is currently estimated. Soil samples are scheduled to be collected on 3/30/2026 to confirm that impacted soils have been removed.			
Soil/Geology Description:			
Vonid sandy loam, 0 to 5 percent slopes, SC-SM NRCS Rating			
Depth to Groundwater (feet BGS) <u>52</u>		Number Water Wells within 1/2 mile radius: <u>0</u>	
If less than 1 mile, distance in feet to nearest		Water Well _____ None <input checked="" type="checkbox"/>	Surface Water <u>4377</u> None <input type="checkbox"/>
		Wetlands <u>4377</u> None <input type="checkbox"/>	Springs _____ None <input checked="" type="checkbox"/>
		Livestock _____ None <input checked="" type="checkbox"/>	Occupied Building _____ None <input checked="" type="checkbox"/>
Additional Spill Details Not Provided Above:			
Location is within Lesser Prairie Chicken Estimated Occupied Range and Lesser Prairie Chicken Connectivity Area HPH			

### CORRECTIVE ACTIONS

#1 Supplemental Report Date: 03/27/2026

Root Cause of Spill/Release Pipe, Weld, or Joint Failure

Other (specify) \_\_\_\_\_

Type of Equipment at Point of Spill/Release: Other

If "Other" selected above, specify or describe here:

Off-Location Flowline

Describe Incident & Root Cause (include specific equipment and point of failure)

After discovery of the leak, the investigation discovered that leak was from a dressing sleeve that had been placed on the off-location flowline prior to Rampike acquiring the location.

Describe measures taken to prevent the problem(s) from reoccurring:

The dresser sleeve has been removed and the flowline has been properly repaired with fiberglass Centron 450 grade. Rampike has communicated Joe Maclaren, ECMC Integrity Inspector, to discuss potential COA's. Soils have been excavated; manifests and soil volumes will be provided in the next supplemental Form 19.

Off-Location is currently inactive and will be pressure tested on 3/30/2026 to confirm repairs.

Volume of Soil Excavated (cubic yards): \_\_\_\_\_

Disposition of Excavated Soil (attach documentation)  Offsite Disposal  Onsite Treatment  Other (specify) \_\_\_\_\_

Volume of Impacted Ground Water Removed (bbls): \_\_\_\_\_

Volume of Impacted Surface Water Removed (bbls): \_\_\_\_\_

### REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

- Basis for Closure:
- Corrective Actions Completed (documentation attached, check all that apply)
    - Horizontal and Vertical extents of impacts have been delineated.
    - Documentation of compliance with Table 915-1 is attached.
    - All E&P Waste has been properly treated or disposed.
  - Work proceeding under an approved Form 27 (Rule 912.c).  
Form 27 Remediation Project No: \_\_\_\_\_
  - SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

### OPERATOR COMMENTS:

\_\_\_\_\_

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Amber Barnett

Title: Compliance Specialist Date: 03/27/2026 Email: abarnett@ardorenvironmental.com

**COA Type****Description**

	Confirmation soil samples shall be collected from areas exhibiting the highest degree of impact.  Operator shall define the vertical and lateral extent of impacts to soil.  Operator shall collect confirmation soil samples for Full Table 915-1 Contaminants of Concern
	Operator shall provide additional information once initial investigation is completed to include any changes to volumes, spill path, root cause, and preventative measures implemented to prevent future reoccurrence at this site and others.
	All previously, assigned COAs shall apply.
3 COAs	

**ATTACHMENT LIST****Att Doc Num****Name**

404597697	SPILL/RELEASE REPORT(SUPPLEMENTAL)
404598192	TOPOGRAPHIC MAP
404598201	AERIAL IMAGE
404598202	PHOTO DOCUMENTATION
404602740	FORM 19 SUBMITTED

Total Attach: 5 Files

**General Comments****User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)